Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: LIFFRIG 29-20 6TFH

Field Name: ALGER Well File #: 26967

Date Incident:8/30/2015Time Incident:14:30Facility ID Number:County:MOUNTRAILTwp: 156Rng: 93Sec: 29Qtr:

Location Description: All fluids contained on location

Submitted By: Mark Turnley Received By:

Contact Person: Mark Turnley

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 2 Barrels 2 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No immediate risk observed

Areal Extent:

All fluids contained on location

Potential Environmental Impacts:

No potential of environmental impact

Action Taken or Planned:

Replace Vic T and sending failed Vic T in for evaluation of failure

Wastes Disposal Location: IHD

Agencies Involved:

Updates

Date: 9/3/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an equipment failure, remained on location according to the report. NDIC retains oversight.